

Wood Venetian Tilting Troubleshooting

Below are 2 pictures of inside a Sunwood headrail

Picture 1—correct ladder cord attachment

Picture 2—incorrect ladder cord attachment— the cause of tilting problems

Picture 1 CORRECT



Picture 2 INCORRECT



Step by Step instructions


If your sunwood blind is not tilting correctly and inside the headrail looks like picture 2, raise your blind up to the lock position



Then using a pointed item or Fingers lift the cord that is trapped and place back onto barrel, need to be careful they don't break the cord.



Once you drop the blind check inside the headrail again and should look like attached picture and blind should be tilting correctly now and fault recti-



If the blind still does not tilt correctly, please contact Customer Services to arrange a collection for inspection and repair

Issue 2

Creation Date: 20/11/08